# Split a Mix

## PAINTMANAGER® XI Software

Undercoat, Color, and Clear layers can be split to multiple Jobs. The split can be performed on the Mix Summary during a mix or from the Job layer tab after a mix.

**1** On the Mix Summary screen [ Split Mix ]

         *Or*

On the Tools menu in the Job layer screen [ Split Mix ]

**2** Select Jobs

    *Or*

**3** Search for Jobs

Once a job is located, clear the search and search for another Job

**4** Next

Step 1: Select jobs to be used for splitting the mix. [Next] [Cancel]

**3** RO Number — Search for Jobs   **4** ⊗

| | RO# | CUSTOMER | VEHICLE | PRIORITY | DUE DATE |
|---|---|---|---|---|---|
| ☐ | 1002 | Customer 2 | 2013 Ford F150 | Normal | |
| ☑ | 1003 | Customer 3 | 2009 Suburu Outback | Normal | |
| ☐ | 100? | Cu... | ...dyundai Sante Fe | Normal | |
| ☑ | 1006 | Cu... | ...Mazda Mazda3 | Normal | |
| ☐ | 1008 | Customer 8 | 2015 Chrysler Journey | Normal | |

Clear search to start an additional search.

**2** Select one or more Jobs

**5** Enter amount to split

     *Or*

**6** Weigh product

Step 2: Verify the amounts to be applied to each job. [Next] [Cancel]

**8**

Note total available → Available Amount 30 floz

🗀 1003
👤

**5** Enter amount to split   [ − 10 + ] [U.S. Fluid Ounces ▾] [▤] [Weigh]

🗀 1006   **7** ✕
👤

[ − 10 + ] [U.S. Fluid Ounces ▾] [▤] [Weigh]

Note total split → Total Poured 20 floz   **6**

**7** Remove Jobs if needed

**8** Next

Step 3: Finish

Remaining Amount     10.0 floz

**9** [Finish]

**9** Finish