



Ref: 20924_Cover Letter Rev A

Email: buildingsafetyteam@networkhomes.org.uk

Date: 03/05/2022

Network Homes – Building Safety Team The Hive 22 Wembley Park Boulevard London HA9 0HP

Dear Network Homes,

Eaton Plaza, EWS1 Form: External Wall Review

Further to client information review and site visits IFC have issued the following report and associated External Wall System (EWS) 1 Forms:

- Report titled "Eaton Plaza, Fire Safety Review of External Walls and attachments" reference FSA/20924/02 dated 25th September 2020
- EWS1_20924_01 Network Oxford Ct(1.0)
 - Oxford Court, Elmfield Way, London, W9 3UG
 - Option B1
 - Date: 28th September 2020
- EWS1_20924_02 Network Leicester Ct(1.0)
 - Leicester Court, Elmfield Way, London, W9 3UJ
 - Option B1
 - Date: 28th September 2020
- EWS1_20924_03 Network Kennet Ct(1.0)
 - Kennet Court, Elmfield Way, London, W9 3UH
 - Option B1
 - Date: 28th September 2020
- EWS1_20924_04 Network Fazeley Ct(2.0)
 - Fazeley Court, Elmfield Way, London, W9 3UF
 - Option B1
 - Date: 28th September 2020
- EWS1_20924_05 Network Welford Ct(1.0)
 - Welford Court, Elmfield Way, London, W9 3UE
 - Option B1
 - Date: 28th September 2020
- EWS1_20924_06 Network Avon Ct(1.0)
 - Avon Court, Elmfield Way, London, W9 3UD
 - Option B1
 - Date: 28th September 2020



International Fire Consultants Limited Park Street Business Centre, 20 Park Street Princes Risborough, Buckinghamshire HP27 9AH Registered No: 2194010 England and Wales



I would also confirm that the review that we carried out confirmed that, in IFC's view, the fire safety risk presented by the external walls and attachments complied with the guidance of MHCLG Advice Note titled "Advice for Building Owners of Multi-storey, Multi-occupied Residential Buildings" dated January 2020. Specifically, that applies to Sections 1 to 7 and 11 of that document (Section 8 relates to the structural performance of external walls, Section 9 relates to Smoke Control Systems and Section 10 relates to Fire Doors and so those sections were not covered by this letter).

The report was reviewed and the forms were signed by my colleague Hugh Forster who is a Chartered Engineer registered with the Institution of Fire Engineers. Since the issue of those document Hugh has left IFC. The fact that he has left the company does not affect the validity of the report and forms.

I would note that the Advice Note mentioned above was withdrawn in January 2022 due to the publication of PAS 9980, but at the time of issue of those documents, the Advice Note was current. I am a Chartered Engineer with the Engineering Council, registered with the Institution of Fire Engineers, registration number: 00024756.

I am a Head of Technical at International Fire Consultants Ltd. which is a fire engineering consultancy company that has been specialising in fire engineering in the construction industry for over 30 years.

Yours sincerely,

Jon Pagan MA(Cantab) CEng MIFireE Head of Technical International Fire Consultants Ltd. (IFC)

